


TWO-LANE NORTH BORE (OAKLAND SIDE)


EXISTING CONDITION






TWO-LANE NORTH BORE (OAKLAND SIDE)
SIMULATED CONDITION-TEN YEARS POST CONSTRUCTION






THREE-LANE NORTH BORE (OAKLAND SIDE) EXISTING CONDITION











TWO-LANE NORTH BORE (ORINDA SIDE)

EXISTING CONDITION





TWO-LANE NORTH BORE (ORINDA SIDE)
SIMULATED CONDITION-TEN YEARS POST CONSTRUCTION





THREE-LANE NORTH BORE (ORINDA SIDE) EXISTING CONDITION





THREE-LANE NORTH BORE (ORINDA SIDE)
SIMULATED CONDITION-TEN YEARS POST CONSTRUCTION

